

Marker Kingpin 10, Kingpin 13 and Kingpin Mwerks Boots Compatibility

Brand	Model	Compatibility	Comment
Arcteryx	Procline Carbon Lite	Yes	DIN Adapter necessary but it causes small scratches at boot front, no effect on releasing and performance
Atomic	Backland / Backland Sport (Old Shell)	Yes	DIN Adapter necessary but it causes small scratches at boot front, no effect on releasing and performance
Atomic	Backland Carbon / Backland Pro / Backland Pro W / Backland Expert (new shell 19/20 and	No	
Atomic	Hawx Ultra XTD	Yes	
Atomic	Waymaker	Yes	
Black Diamond	Quadrant	Yes	
Black Diamond	Prime	Yes	
Black Diamond	Swift	Yes	
Black Diamond	Slant	Yes	
Dalbello	Krypton 130 T.I. / Chakra Elevate 115 T.I.	Yes	
Dalbello	Lupo line / Lupo AIR / Lupo MX	Yes	
Dalbello	Quantum / Quantum LITE / Quantum FREE	Yes	
Dynafit	Beast / Beast Carbon / Beast Damen	No	
Dynafit	DANN	No	
Dynafit	DY.N.A	No	
Dynafit	Hoji Free	Yes	
Dynafit	Hoji PU / Hoji Pro Tour / Hoki	No	
Dynafit	Khion	No	
Dynafit	Mercury	Yes	
Dynafit	Neo / One PX	Yes	
Dynafit	PDG	No	
Dynafit	Radical	Yes	
Dynafit	Titan Ultralight	Yes	
Dynafit	TLT 5 / TLT 6 / TLT Speedfit	Yes	DIN Adapter necessary
Dynafit	TLT 7 / TLT 8	No	
Dynafit	Vulcan	Yes	
Dynafit	Winter Guide	Yes	
Fischer	Transalp Vacuum	Yes	
Fischer	Travers	Yes	
Hagan	Core	Yes	
K2	Minaret 100	Yes	
K2	Mindbender (all models)	Yes	
K2	Pinnacle 110 / Pinnacle 130	Yes	
La Sportiva	Shadow	Yes	
La Sportiva	Sideral	No	
La Sportiva	Sparkle	No	
La Sportiva	Sparkle 2.0	Yes	
La Sportiva	Spectre	No	

La Sportiva	Spectre 2.0	Yes	
La Sportiva	Spitfire	No	
La Sportiva	Stratos	No	
La Sportiva	Syborg	No	
La Sportiva	Synchro	Yes	
La Sportiva	Sytron Allround	No	
Lange	XT 110 / XT 130	Yes	
Movement	Alp Tracks Explorer / Alp Tracks Explorer Wmn / Alp Tracks Performance / Alp Tracks Performance Wmn	Yes	
Movement	Free Power 3	Yes	
Movement	Free Touring 3	Yes	
Nordica	Strider	Yes	
Roxa	Evo	Yes	
Roxa	X Face Tour / X Face 120	Yes	
Roxa	XW 1.0	Yes	
Salomon	MTN Lab / MTN Explore	Yes	
Salomon	Quest	Yes	
Salomon	S-LAB X- ALP	Yes	DIN Adapter necessary but it causes small scratches at boot front, no effect on releasing and performance
Scarpa	Alien 1.0 / Alien 3.0 / Alien RS	No	
Scarpa	F1 / F1 Wmn	Yes	
Scarpa	F1 Evo / F1 TR / F1 LT	No	
Scarpa	Flash / Magic	Yes	
Scarpa	Freedom RS / SL / SL wmn	Yes	
Scarpa	Gea / Gea RS / Gea GT / Gea 2	Yes	
Scarpa	Maestrone / Maestrone RS 2	Yes	
Scarpa	Spirit TR 2	No	
Scarpa	Vector Wmn	Yes	
Scott	Celeste I / II	Yes	
Scott	Cosmos / Cosmos II / Cosmos III	Yes	
Scott	Orbit / Orbit II Carbon	Yes	
Scott	Phantom	Yes	
Scott	Phantom	Yes	
Scott	Superguide Carbon	Yes	
Tecnica	Cochise Pro Light Dyn / Cochise Pro Light Dyn W	Yes	
Tecnica	ZERO G Guide	Yes	